# **Tester**

# Resistance Measuring Instrument

Antistatic Shoe Leakage Measuring Instrument








### **Application Example**

- Semiconductor manufacturing plants
- Paint plants
- Plants where hazardous products such as solvents or powder are handled and the wearing of antistatic shoes is required.


## **Dimension Diagram**



### **Main Features**

The SHOE TESTER is a dedicated measuring instrument that measures the electrical resistance of antistatic shoes designed to eliminate static electricity from the human body, while the shoes are being worn. To perform measurement, the person wearing the shoes stands on the base and operates the instrument simply by pressing the touch panel with one finger.

A resistance of 100  $M\Omega$  or less to ground is required to eliminate static electricity from the human body, and at least 0.1  $M\Omega$  is desired for the prevention of electrical shock. Since the resistance of the shoes will vary depending on the temperature and humidity, dirt on the shoe soles, and friction, periodic measurement and maintenance is required.



### **Specifications**

Model		SHOE TESTERII
Measurement method		Resistance measurement using a transistor DC converter,
		analog comparison method
Measurement voltage		10VDC
Measurement accuracy		±10%+2digits
Measurement range		0.00~200.0ΜΩ
Display		3-1/2 digit red LED display, automatic decimal point setting
Limit settings	Upper limit value	$1M\Omega / 5M\Omega / 10M\Omega / 20MΩ / 35MΩ / 50MΩ / 100MΩ$
	Lower limit value	0.1 MΩ / 0.5 MΩ / 1 MΩ / 5 MΩ / 10 MΩ
		Cannot settings upper and Lower limit value
Alarm		The green lamp is lit during normal recording
	Upper limit value	The red lamp lights and a buzzer (with on/off switch) sounds
	Lower limit value	The red lamp lights and a buzzer (with on/off switch) sounds
Function check		Ohm check switch, 0.95~1.05MΩ
Battery check		Push-button method
Power supply		DC12V ACadapter (100~240AC)
Operating Environment		0~40°C
Dimensions		Main unit: 170×140×37 (W×H×D)
		Measurement stand: 310×350×30mm (W×D×H)
Weight		Main unit 0.9kg Measurement plate 4.5kg Measurement stand 1.2kg

